

YEAR: DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
2021 Sept 15	1844.7			Engine oil and filter changed. Filter p/n AA48105-2 Serviced with 9 qts Phillips x/c 20W-50. <i>Scott Cozy Howarr 3673526</i>

Total time: 1847.7 Hours
Date: May 27, 2022
Registration: C-GPJV

Annual inspection completed as per CAR 625 B & C. Air filter cleaned IAW manufacturer's instructions. Engine oil drained and filter changed. AA48105-2 filter installed, serviced with 9 qts. Phillips X/C 20W50. Engine washed and leak checked serviceable. Compressions: #1- 78/80 #2- 77/80 #3- 76/80 #4- 79/80 #5- 78/80 #6- 77/80.

This engine will be maintained in compliance with Canadian Air Regulation 625, Appendices B & C.

An import inspection has been performed on this engine, as per CAR 625, Appendices B & C and the requirements.

Scott
Scott Howarr

AA42573

YEAR: DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
2021 Oct 17/23	1061.9			Added Lt. Phillips x/c 20W50 <i>Scott AA42573</i>

ws_002_721

888-4400

Engine page 1 of 1

Gibson Aviation Services 1400 Indianapolis Dr. East Menomonee, WI 54751 7152211638

C-GPJV
TACH: 1062.3

July 29, 2022

Performed fuel setup IAW SID97-2 and TCM M-18. Leak and functional check satisfactory.
With respect to the work performed, this engine is approved for return to service.

Aaron Simmons A&P/IA 3592994 *AS*

2021/11/26	1070.5			Added Lt. Phillips x/c 20W50 <i>Scott AA42573</i>
------------	--------	--	--	---

Date: 12/26/2006

Signed *James Hooper*

Inspector for Premier Aircraft RS JZYR537L

